# TRIBOMAR®

## USB Connect with TriboLab³ device

Connect the device with an USB-C cable to the PC (Connector on the back)




To transfer the data from your TriboLab³ device to PC, please install Tribomar Software from enclosed USB-Stick










Setup - Tribomar version 1.80
Ready to Install
Setup is now ready to begin installing Tribomar on your computer.
Click Install to continue with the installation, or click Back if you want to review or change any settings.
Destination location:
C:\Users\AppData\Local\Programs\Tribomar
Additional tasks:
Additional shortcuts:
Create a desktop shortcut
Back
Install
Cancel


Setup - Tribomar version 1.80
Completing the Tribomar Setup Wizard
Setup has finished installing Tribomar on your computer. The application may be launched by selecting the installed shortcuts.
Click Finish to exit Setup.
Launch Tribomar
Finish




Tribomar Software Window starts with connected TriboLab device




Set actual date and time

Export data to PC

stored data

Loading data

Save data







Choice to delete all data or not

# Troubleshooting

If COM Port does not show a device and loading bar stops @ 50% then check your **anti virus protection**

If still no progress then check Windows Device Manager for Ports (COM & LPT) / Silicon Labs CP210x must be shown



# Troubleshooting

Install Silicon Labs CP210x if error occurs (message – device is not working properly) from USB Drive




If requested restart your PC

**TRIBOMAR** ®
onboard fluid management

Biedenkamp 3e
D-21509 Glinde/Hamburg
Germany
Tel: +49 40 7309 1399 0
Email: info@tribomar.com